


4. Please check if the corresponding output control points in Rebocap software are either multi-selected or unselected



Body and headset are not facing the same direction.